

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler spaces.

See Special Survey. Date of last Survey and of Periodical Surveys.



Lloyd's Register of Shipping

JACK CORBU
SURVEYOR
DISTRICT
MOUTHS OF RIVER DANUBE INCLUDING SULINA,
BRAILA, GALATZ AND CONSTANTZA
RESIDING AT BRAILA
TELEGRAMS "JACK CORBU"

Braila, 16th January, 1937.

LLOYD'S REGISTER
RECEIVED
19 JAN 1937
ANSA. 21.1.
LONDON

Plans

Dear Sir,

I have the honour to forward herewith the letter which I have received from the Owner of the s.s. "HANNE" regarding the conversion of the boilers to oil burning together with two plans of the proposed alterations to the cross bunker to be used as an oil fuel bunker.

While at Constantza I examined the vessel and discussed the matter with the Owner. He is anxious to receive your reply at the earliest date as the vessel is laid up at Constantza, awaiting your approval to begin the work.

I am, Dear Sir,

Yours faithfully,
Jack Corbu

The Secretary,
Lloyd's Register of Shipping,
LONDON, E



© 2019

Lloyd's Register
Foundation

W178-0026

Fee (per s...)
Damage or Repair Fee (if any).....£
Received by me.....19.....

(Inclu...
Ship...
Wood Vess...
Month...
tain...
remov...
Riggin...
Book cor...
and to b...
Boor...

referred to the Chief Surveyor
and the Chief Engineer Surveyor.

referred to the Chief Engineer Surveyor

H/B
Urgent

19 JAN 1932

[Faint, mostly illegible handwritten text, possibly bleed-through from the reverse side of the paper.]



© 2019
Lloyd's Register
Foundation

NGU
Six
New
rs