

Ref Surveyors _____

Received from Chief Surveyors _____

NAME Steel S.S. "HARMONIDES" Report Gls. No. 39560.

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/2.)

of Survey _____

When due _____

The Downston Pump has been dispensed with for the present, but it is concluded Owners are agreeable to fit same when requested.

100 A.1. (steel).

2 Dks. (steel).

Cell DB 340' 1134t. FPT 128t. APT 200.

FK. 7BH. Com. Lloyd's A&C.P. P49, B 113, F39.

M *as* 29-1-20

It is concluded the widths of the bottom plating are less than 84 inches in view of butts being quadruple nicked, also that the riveting in edges of sheerstake and bridge side plating and ⁱⁿ edges of stake below sheerstake clear of bridge is as required, but the Surveyors should be requested to state if this is so.

It should be pointed out to the surveyors that the Nos of Anchor certificates & weights of Anchors given in this report are the same as given for "Harmothius" (Gls. report No 39259) & they should state to which vessel these Anchors were supplied & give particulars of Anchors supplied to other vessels.

by 5/2/1920



© 2019

Lloyd's Register Foundation

W178-0216