

2m, 10, 38.

1  
Sent to Chief Surveyors

The vessel placed in dry dock, the shell plating rudder clean  
Received from Chief Surveyors 23 SEP 1940

VESSEL'S NAME

CLONLARA

Report LIV

No. 114803

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DOCKING

When due

Subject to starboard side plating etc (set in) being permanently repaired at the first convenient opportunity.

WAS  
21.9.40



© 2020

Lloyd's Register  
Foundation

W18 - 0002

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register for this survey, thus, for example:—".....to remain as classed in the Register Book without fresh record of Survey," "to remain as classed