

1

Sent to Chief Surveyors.....

Received from Chief Surveyors..... - 2 MAR 1942

N.Os 5517

Gls No. 65133

VESSEL'S NAME..... INGERTO

REPORT

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey GEN. EXAM. &amp; COMP. OF 2ND S.S. When due No. 2 DUE 5.40

Subject to the side bunkers being examined at the first opportunity (and to 30 fathoms of chain cable being supplied).


(Length and mean diameter of the chain cables to be ascertained).

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.

It is submitted the Certificate be withheld pending the Examination of the Side Bunkers.

*WAB*  
26.2.42

*Italics put*



© 2019

Lloyd's Register  
Foundation

W180-0 216