

Lloyd's Register 1 JAN 1926

Glasgow, 31st December, 1925.

Chief Surveyors \_\_\_\_\_ Received from Chief Surveyors \_\_\_\_\_

NAME Stl S. M. V. KING MALCOLM Report Sls No. 45270

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Survey 1<sup>st</sup> Entry When due Revised Rules

✝ 100 A.I. (Steel) "With Freeboard"

1 dk (Stl) + Shelter dk (Stl) . 2<sup>nd</sup> dk (Stl) in No 3 Hold.

+ Web frames, Longitudinal framing in double bottom and at decks "Corrugated Sides"

Cell D.B 334' 1227t, D.T.f 53' 1050t, F.P.T. 95t, A.P.T. 220t.

F.K., 7B.H (Collision B.H. to Shelter D<sup>c</sup>), pt cem, Lloyds A.C.P.

F 36.

*23/1/26*

*Yes see letter*



© 2019

31.12.25

Concluded the thickness of the Centre Section is as approved for the sister vessel the Surveyor should be requested to state if this is so.

Lloyd's Register Foundation  
W184-0170

W184-0172