


Messrs. Swan, Hunter & Wigham Richardson's Yard No.1555

Mr. Inman, representing the Builders, telephoned this Office today and requested to be informed if the number of rivets in the lugs attaching the bottom longitudinal to the transverses could be reduced to 6 from 8 as shewn on the plan of midship section.

It is submitted the Builders be informed that as the Rule depth of longitudinal is 14" the number of rivets in the lugs attaching the ^{bottom} longitudinal to the transverses may be 6.

Ltr. 16.9.37.
P.C. Nwc.

J.R.
[Signature]
15.9.37.



© 2020

Lloyd's Register
Foundation

W186-0329