

Damage due to vessel striking
quay wall.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damaged as to spread the ink, or to cause it to show through to the other side.

Screw shaft, propeller, sea
connections & outside fastenings &c.
a new propeller fitted.

For endorsement see
First Entry Report
attached.

JWD.
2/3/28.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation