

1. Annual Survey of Examination and Repairs (if any) less Donkey/Boiler  
 (Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and

55CM 103  
 55CM 102

W198-0133

Rpt. 7a.

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office \_\_\_\_\_ 19\_\_

# Lloyd's Register of Shipping.

(Report on Machinery, No. 86376. Port Newcastle)

No. F4797

## ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by Walter Tappin & Engineering Works Ltd. of London.

for the Engines or Boilers No. \_\_\_\_\_ being constructed by SS "MAROUSSIO COULOUTHROS." of \_\_\_\_\_

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to Super Dry and Supt.

Stamp Mark.

LLOYD'S TEST.  
400 lbs.  
 No. 5974  
 T.S. 20-10-30

L. W. H.  
London  
 22. 10. 30

Number and Description.	<u>1- 2 1/2" Double Safety Valve Chest.</u> <u>C.I.</u>
Hydraulic Test: lbs. per square inch.	<u>400 lbs.</u>
Other Tests, if any.	<u>✓</u>
Dates when Inspected.	<u>20-10-30.</u>



© 2020

Lloyd's Register Foundation

Fee: - £1-1-0. Applied for 22 OCT. 1930

and safety valves being fitted to the new donkey boiler at the fire