

3 AUG 1942

m,5,42

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "MUNDRA" REPORT Cal. No. 11590C

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to bow plates being further examined and dealt with as necessary at the first opportunity.

The CALCUTTA Acting Surveyors report on Form 10 the vessel placed in dry dock and minor repairs effected.

The butt strap of coffin plate aft, found corroded through, has been temporarily repaired, a new butt strap has been made and placed on board the vessel and the Surveyors recommend this be fitted at the first opportunity. (1)

The crown shackle pins of both anchors found slack and it is recommended these be attended to at the first opportunity. (2)

It is submitted the vessel appears worthy to remain as classed and to have record of docking survey 5,42 subject as recommended (1) & (2) and as above.

100A1) Subject etc.
5,42 Cal.)



21
4.8.42
Lloyd's Register
Foundation
199-0018

A new butt strap was made and has been placed on board the vessel to be fitted at the first suitable

ing and Running