

15 OCT 1917

Received by Chief Ship Surveyor 15.10.17

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S.S. "DIYATALAWA" Rpt. Bom. No. 2291

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Examination for G.L.

This vessel was built in 1912 and classed with Germanischer Lloyds.

The Bombay Surveyor now reports the vessel has been placed in dry dock, the bottom cleaned and coated.

One plate in "A", "B", "C" & "D" strakes found badly indented.

Temporary repairs are stated to have been carried out at Newcastle in December 1915, *now examined found efficient*

The holds, 'tween decks, fore & after peaks, decks, Engine & Boiler spaces & casings, bunkers, hatches, & hatch coamings, examined & found satisfactory.

The bunkers require scaling.

The steering gear, windlass & watertight doors examined and found in order.

It is submitted the notation of "G.L" Bom, 8. 17, be assigned.

G.L. Bom 8. 17.

[Signature]
15. 10. 17
[Signature]

Surveyor requested to advise amount of payments of fees 19/10/17



© 2020

Lloyd's Register Foundation

W 202 0085