

The Class is Subject to the 2nd intermediate Shaft
from forward being examined before end of 5.44

5 E

7 MAR 1944

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

Panos.

Rpt.

H/c

No. 4732.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

of Survey


DAMAGE & WEAR AND TEAR.

Auxiliary feed pump valve chest repaired

It is stated a new feed pump will be fitted at first opportunity
the present temporary repairs now effected are satisfactory

It is submitted the vessel is eligible to remain as classed with
record of Survey Subject as recommended. above.

S.P. No 2 Dec 7.44



© 2019

Lloyd's Register
Foundation

W 205-0072