

pipes and electric installation has been examined
and found satisfactory.

See also New York Report No 32615

The Doukey Boiler has been removed from the ship

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2019

Lloyd's Register
Foundation