

Extract from letter dated: 27.4.42.(Air Mail).  
from: New York Surveyors.  
original with "S."  
Vessel's name M.S. "SILVERAY" L.ANG.2776.

The assignment of the fresh under-date of 6/41 is noted, and the Surveyor advises that the renewal of the auxiliary engine crankshaft was due to the considerable amount that the crankpins, and to some extent the main bearings, were worn out of truth. As the spare shaft was available, it was decided to have it fitted in place of the worn shaft. It was understood the Owners would have the removed shaft machined true at their convenience.

*W. H. H. H.*



© 2019

Lloyd's Register  
Foundation

W 217-0001

K SECTION NO