

COPY.

Lloyd's Register of Shipping.



Port

Vancouver, B. C.

February 3rd, 1936

This is to Certify that I have

Surveyed the Boiler and Machinery of the M.V. "SILVERAY" 4536
tons gross of London on dry dock. Screw shaft drawn, sea
connections and part Continuous Survey.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of L.M.C. (C.S.) 2,36

be made in the Register Book in the case of this vessel when
the survey has been completed, and notations C. L. 1,36 and
D.B.S. 1,36.

Parts now examined:—

Annual survey of donkey boiler.
New exhaust gas heater fitted.

No.2 main bearing examined and lower half remetaled.
Thrust shaft and bearing examined.
Attached jacket water pump examined. New brass liner
and rod fitted.

A. Scott

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register of Shipping.

PARTS EXAMINED - Cont'd.

VERIFICATION, E. C.

Part

No.1 Generator - Crank shaft trued up. All main bearings remounted.

No.3 Generator - opened up and examined throughout. Also examined under running conditions.

Examined separate Bilge Pump

and that I have

Examined the Boiler and Machinery of the "M.V. 'SILVER' 4335"
Examined condenser. Tube plate refitted, tubes renewed.
Examined evaporator and mountings.
All sea connections examined.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have recommended that the record of M.V. (C.S.) 4335

be made in the Register Book in the case of this vessel when the survey has been completed and notation C.S. 1336 and D.B. 1336.

Parts now examined:—

Annual survey of donkey boiler.
New exhaust gas heater fitted.
No.2 main bearing examined and lower half remounted.
Thrust shaft and bearing examined.
Attached jacket water pump examined. New brass liner and rod fitted.

John

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

