

Looking after collision
Ship's side discharge valves refitted

No. 2 due 9.39

G.E. now held.

It is submitted that
this vessel is eligible for
THE RECORD.

Examined 542-1300

Subject to propeller
bores being specially
examined at next
dry docking

[Signature]
11/6/42



© 2019

Lloyd's Register
Foundation