

-5 DEC 1941

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME TACOMA STAR REPORT Liv No. 116979

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

f Survey DAMAGE When due

Subject to indented shell plate No. 3 in 4th strake below sheer, forecastle side and sheerstrake plating (p.s), indented shell plates K.11 and 12 (s.s) and No. 2 main sheerstrake plate etc. (s.s.a), distorted boiler casing in 'tween decks being dealt with, and to all D.B. tanks being examined internally (grounding) at the Owners' convenience, and to a ventilator coaming on the after deck being refitted at the first opportunity.

PLATING to be DRILLED when vessel is 24 years old, or at next Special Survey thereafter.

Wab
2.12.41



© 2019

Lloyd's Register Foundation

W223 0060