

1

Surveyors 11. 10. 18

Received from Chief Surveyors

NAME Stl. S.S. "TJILECOEL" (?)

Report

Rot.

No. 10622.^aFor the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey

When due

It is submitted before this case receives consideration, the Surveyors should be requested to state whether they are correct in reporting the thickness of the tank top plating in the Engine space as .44 .

The Surveyors should also forward a sketch showing the positions of the side girders and ~~side positions~~ of the manholes fitted in the double bottom *floor*

11. 10. 18

© 2019

Lloyd's Register
Foundation

W223-0195