

s.s. "VEERHAVEN".

Repair to Boiler shell plate.

IT IS SUBMITTED the Antwerp Surveyors be informed the remarks contained in their letter of the 9th instant, and the enclosure, have been carefully examined.

With reference to the proposal to remove a portion of the butt strap only, it is desired to point out that since there is reason to think that cracks exist in the shell plate in way of the butt straps, see Mr. McKinlay's letter of 19.12.35., the actual condition of the plate can only be revealed by complete removal of the butt straps.

16.1.36.



© 2019

Lloyd's Register
Foundation

W226-0153