

S.S. "VIKINGSTAR"

The S.S.No.1 became due last month. The survey of the screw shaft became due in March, 1923, and is therefore more than 12 months overdue..

The Owners state that they had made arrangements to have the screw shaft surveyed during the vessel's lay up at Liverpool but owing to the dock strike they were unable to do so..

They had again made arrangements for this survey to be held in London this voyage, but owing to one of the vessels they had chartered having a breakdown, they are anxious to replace her by the "VIKINGSTAR"..

They request that in the circumstances the survey of the screw shaft may again be postponed until, the vessels return from the River Plate in two months' time..

This case is submitted for the consideration of the Committee..

ARH

30. 4. 24.

Should be done before sailing

[Signature]

Lr Owen 30/4/24

W228-6149

© 2019

Lloyd's Register
Foundation