

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 5th Sept. 1935 When handed in at Local Office 6/9/35

Port of

NEWCASTLE-ON-TYNE

No. in Survey held at South Shields

Date, First Survey

(No. of Visits)

and, Last Survey 4th Sept. 1935

37010

on the ~~Wood, Iron or Steel~~

AURETTA

TONNAGE:-

Built at Burntisland

By whom Burntisland S.S.Co.Ld.

When 1935

GROSS 4500

Owners Calpean Shipping Co. Ld.

Owners' Address

(if not already recorded in Appendix to Register Book).

UNDER DK. 4245

Managers

Port belonging to Gibraltar.

NET

Surveyed Afloat or in Dry Dock? Dry Dock

Name of Dock Middle Dock

Destined Voyage 1

WB=CellDBorDBa

feet; uE&B

feet; f

feet

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No.

Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER
* for Special Survey
Date of last survey and of
Periodical Surveys.Year
Assigned
now
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

100A1

with freeboard

(Class contemplated)

Society's Freeboard (if assigned) as
painted on Ship and now verified

ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

None Done! Vessel placed in dry dock, bottom keel and rudder cleaned examined found in good condition and correct. The rudder was not lifted.

SUMMARY OF DAMAGE REPAIRS:-

Renewed
Removed and Faired or Repaired
Faired or Repaired in place

Shell Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams & Fastenings

Outside Plating

" " in way of sidelights

Breasthooks

Transoms

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Ventilators and their Coamings been examined

and found efficient?

Air and Sounding Pipes

Dbing. Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking of Wood/Vessels

Caulking

Treenails

Breasthooks & Stems

Transoms Pointers, & Brutes

Timbers of Frame at openings

Ditto Ditto at other places

Stringers, Clamps & Shells

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Ball)

When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Chain Locker

Cables (State if now ranged)

" length

(on board)

" Rule length

Hawser & Warps

Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and pND24, &c."

This vessel as far as now seen is in a good and efficient condition and eligible in my opinion to remain as classed with fresh record of survey 9.35.

Survey Fee (per Section 20) £

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19


Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. 24 SEP 1935

Character Assigned

see Lth. J.E. 18899

Lloyd's Register
Foundation

W230-0288

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

CHAIN CABLES.

[illegible]

Iron Stream Chain }
or Steel Wire... }