

2m.12.42.

Received by Chief Ship Surveyor.....

VESSEL'S NAME "ANTIGONE"

Received from Chief Ship Surveyor.....

E-1 JUN 1943

REPORT St.J.

No. 342

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 1st S.S. No.3 due 5.40 has been partly held.
Notation of 'Examined 12.42' valid for 12 months
has been assigned.

For conditions of class see previous endorsement.

The SAINT JOHN N.B. Surveyors report (4.43) the vessel examined afloat on account of damage through heavy weather, ranging and striking wharf and temporary repairs effected to stem and stem plating and a double bottom tank air pipe renewed.

The Surveyors recommend permanent repairs at the Owners' convenience.

Minor repairs effected.

It is submitted the vessel appears worthy to remain as classed subject to permanent repairs to stem, stem plating, hawse pipe (p.s.) at the first opportunity, to indented shell plating, bulkhead wing plate etc. (s.s.f) at the Owners' convenience, to indented sheerstrake and deck stringer plating in way, to Nos.1 & 5 hatchways, forecastle side plating etc. at the first convenient opportunity and to fore peak suction pipe being repaired on the vessel's return to the U.K.

As now, subject etc.

AMEND S.R.L.

BTH
31.8.43

Copper, or Y.
(State if on)

When fitted, M

Boats

Masts, Yards,

Condition, how

(State if w

Equipment letter

Anchors, No. c

Cables (State

" length

(on b

" Rule len

Chain Locker

Hawsers & Wa

Standing and R

Sails

this vessel

e vessel in the Register

"to remain as classe

t to indent

ing dealt

stem, stem

rward bulkh

plating (s.s.

portunity; an

"While the Committee executed, it is to be understood that neither whatever to be held responsible for any inaccuracy in any entry in the Register Book or other publication of the Society, or for any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents



© 2021

Lloyd's Register
Foundation

W232-0002