


22 MAR 1935

It is submitted the Falmouth Surveyors be informed the Certificate of Test supplied by the makers of the dynamo has been examined and the results found to comply with the requirements of the Rules. In these circumstances no exception will be taken ^{to the fitting on board of this dynamo}. The Surveyors should, however, point out to the Owners' representatives that it is a requirement of the Rules that generators of 100 K.W. and over are to be inspected by the Surveyors during construction and test and in future cases this requirement should be carried out. It is noted the Sunderland Forge & Eng. Co. state they were not informed that a Lloyd's Certificate was required.

It is further submitted the Stockholm Surveyors be informed that with regard to the oil engine for the above vessel which was dealt with in their report No.3970 the generator coupled to the same was not constructed and tested under survey.

It is a requirement of the Rules that generators of 100 K.W. and over should be inspected by the Surveyors during manufacture and testing, and Messrs. The Sunderland Forge & Eng. Co. state they were not informed by the Atlas Diesel Co. that a Lloyd's Certificate was required in this instance.

The Surveyors should request the Atlas Diesel Co. in future cases to notify their Sub-Contractors of this requirement when machines are supplied for installation in vessels classed or intended for classification with this Society.



© 2019

Lloyd's Register
Foundation

W238-0143