

Engine Room ... 552.54299.43
TONNAGE FOR FEES ... 275.63
Less Engine Room ...
Le...

Upper Deck Deck as side to top of keel 15.46
Remain of Deck (and Bridge Deck) 10.29

Residence

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50

15c, I. 14.

1

Gewbank

Sent to Chief Surveyors 21.5.14

Received from Chief Surveyors

VESSEL'S NAME

Shess Aberdale

Report

6/6

No. 34072

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

1st Enb

When due

100A-1 (Steel)

1DX (Steel) weld dx

WTB - cell 2 B + 95' 1376 FRT 515 OPT 446

BK. 6. 3BH. Cam. Lign. over. @ 96. B9' F32. Incl. abt.

M

The Surveyors should be informed that the test for the steel wire in lieu of ^{up to 1/2" diameter} chain + also for the towline have been ^{made} quarters from their report & requested to forward same.



© 2020
21.5.14

Lloyd's Register Foundation

W260-6047

Fourth and Fifth Deck Stringer Plate.)	
breadth & thickness)	
Angles on ditto, No.	
Spacing	22 ✓
BEAMS, Second Deck, Single Angle, Bulb)	22 ✓