

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME

Shere St. West Island

Report

PLS

No. 561

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

are of Survey

When due

Downton pump dispensed with for the present.
Owner—The Emergency Fleet Corporation.

100A-1. Steel

2 Dks (Steel)

Cele DB 355 1139C MT 29 745C FPT 132C APT 143C

FK. 7BH. pl Cam. axep. P 44. B 115 F 47

W242-0029

MAIN PLATE, depth
and thickness
Angle to Outside

Floors

Brackets at intermdt frms. width & thkns

	3	3	8.3			
	40	48				
4	4	12.8	4	4	12.8	
5	3 1/2	12.0	5	3 1/2	12.0	
	✓	✓		✓		

Second Deck Stringer Plate, or alt & thickness

Angles on ditto, No.

Tie Plates outside Hatchways

Diagonal Stiffeners

© 2020

Lloyd's Register
Foundation