

e to report that the Forgings or Castings are being done.

Grit

Low 104037

How Surveyors state a new auxiliary engine
has been fitted and coupled up to existing dynamo
and under working conditions found satisfactory
as engine replaces one which was damaged.

It is submitted that
this vessel is eligible to
remain as CLASSED.

Yours

15.2.39

Re to 78 report (per Edt)



© 2019

Lloyd's Register
Foundation

180
8.5.36 11/5/36 26/10/36