

s/s "Louis Botha"

It is submitted, the Hull Surveyors should be requested to state, whether 2 Bottom End Connecting rod bolts & a set of feed & bilge pump valves have been placed on board as spare, no mention of them being made in their report.

J R S L

J W D

4/7/16

x 250-0125