

W251-0027(1/2)

COPY.

Lloyd's Register of Shipping.

Port of **ANTWERP**

13th April 1933

This is to Certify that

WILLIAM BRUNETTWAY,

undersigned Surveyor to this Society did at the request of Owners' Superintendent survey the steel twin screw steamer "GOLDVILLE" 11256 tons gross, of Antwerp, whilst lying afloat at Antwerp on the 13th March 1933 and subsequent dates to ascertain nature and extent of the damage stated to have been caused by collision with the quay wall at Antwerp on the 12th February and, (2) collision with the S/S "ERNAH" when the latter was entering the Mercantile dry dock at Antwerp on 23rd 1933.

FOUND

RECOMMENDED

- Starboard Side.** Shell plate No. 6 One shell plate to be renewed, left in the 2nd strake below sheerstrake intented.
- Shell plate in the 3rd strake One shell plate to be faired in the sheerstrake slightly place.
- on the upper edge in way.
- flange of one frame in way One frame to be faired in place.
- ly bent.

W.B.W.

issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is neither the Committee nor the Society are under any circumstances whatever to be held responsible for any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other document, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or of any Officers or Agents of the Society."



W251-0027(1/2)
OCT. 15 SEP 1933

FRI. 13 OCT 1933

W.B.W.

-2- COPY.

FOUND

RECOMMENDED

Lloyd's Register of Shipping

1 plate in the 3rd strake Deck and one shell plate in place. Two shell plates to be faired in place. 4th strake below D. Deck on lower stern slightly indented.

ALSO RECOMMENDED that all fittings necessary to remove plate or effect these repairs be replaced as before, that all disturbed work be coated outside and inside as the whole of the work be carried out so as to place vessel in as good and efficient condition as obtained before repairs were sustained.

FRS.1068.-

N.S. Gray

SURVEYOR TO LLOYD'S REGISTER

ANTWERP.

have transmitted to the Committee of Lloyd's Register, London, a Report stating that all repairs have been completed to my satisfaction, and

recommended that she be continued as fit to receive cargo and passengers.

N.S. Gray *J. L. Rabey*

Surveyor in Lloyd's Register.



© 2019

Lloyd's Register Foundation

W251-0027(2/2)

As now

FEB 12 1933