

No. 18253

(Received at London Office

18 APR 1953

256	Vessel built at <i>Hoboken</i>	By whom <i>See A. J. Beckerill</i>	When <i>1929-8</i>
521	Engines made at <i>Lerouing</i>	By whom <i>A. J. Beckerill</i>	When <i>1929</i>
019	Boilers, when made (Main)		
6	<i>Donkey</i>		

Owners <i>Mar. Lloyd Royal Soc. An.</i> Managers <i>Agence Marit. Internationale</i> If Surveyed Afloat or in Dry Dock <i>afloat in Canal Dock</i> (State name of Dock.) <i>and in Mercantile Dry Dock</i>	Owners' Address (if not already recorded in Appendix to Register Book.) Port <i>Antwerp</i> Voyage	Particulars of Classification (which must be inserted)
---	---	--

No. _____	Port _____	CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years allowed to expire.	Machinery and Boiler Surveys (including date of N.B., if any)
of Examination and Repairs (if any) <i>Condition & Palm oil imp of + 100 Bl</i>				

When held, must be reported in detail and verbatim in the terms of the Rules. State clearly the nature, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on the (the cause of which must be stated) should be separated from Repairs due to other causes; and in the body of the report, should be briefly summarised at the end of the report. State also the any letters respecting this case. *See letter dated 3/4/33 and 4/3/33*

If the Surveyor has not made a special damage report he is required to state whether he has for this purpose, and why they were declined.

with fuel. 8-32
C.L. 8-32.
+ L.R.M.C. 10-32
8-32

made by anyone else? If so, by whom?

ally go inside each Main Boiler separately and make a thorough examination at this time? no

" Donkey " " "

ta for what reasons? 13-1 not done

oilers could not be thus thoroughly examined? ✓

in the absence of internal examination, were adopted by the
 self of the thorough efficiency of those parts of each Boiler? } C

Final examination of each boiler

the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

To what pressure were they afterwards adjusted under steam? 100 lbs

the drain plugs of the Main Boilers? , and of the Donkey Boiler?

all the mountings of the Main Boilers? _____, and of the Donkey Boiler? _____

Is drawn and examined? no. Is it fitted with continuous liner? — Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —

aged? ☒ If so, state reasons _____

been previously used? ☒ Has it a continuous line? ☒ Is an approved appliance for use _____

Is it a continuous liner? _____ Approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? 2

If Screw Shaft _____ State the distance between lignum vitae or bearing metal of stern bush and top of _____ 3 1/2

etc, state what arrangements have been made for its completion and what remains to be done complete / 32

Vessel placed in dry dock. Both propellers after ends of stern

fastenings of sea connections exd.
out and that hid it back

Salm oil in bulk on the Howard towards the 1st

Has been built between the N:1 and N:2 fuel oil tanks

amps and fittings have been installed and tested and are

satisfaction of the undersigned to have been

Plans: N: 1495 - N: 1514 - 903 - N: 1502 - N: 1523

utions, Opinion, and Recommendation:—

quired to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9.11, B.&M.S. 9.11, or S.M.C. 9.11.

It is in a safe working condition, and eligible in our opinion

... as claimed in the Society's Register Book without
of Survey and to have not to be left in the

1st and 2nd fuel oil tanks.

Election for 2100 - Fees applied for 14-4-19 33

Received by me, *Wm. C. Keilley & F. L. Rabalais*

31-5-10-33
TUE. 9 MAY 1933
TUE. 27 MAR 1934
Engineer Surveyor to Lloyd's Register of Shipping.

As now TUE. 12 SEP 1939 Lloyd's Reg

FRI. 18 OCT 1933
TUE. 10 SEP 1933

100-19 DEC 1933