

1E

or Surveyor

Received from Chief Engineer Surveyor

MALA.

Rpt.

Amst.

No. 12474

Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also
it clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points
the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

ine

oil engines. 4 S.C.S.A.

ilers fitted with forced draught

no.

Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

Yes
no.

vessel's machinery appears to have been built in accordance

rules and the approved plans, and it is submitted she is

to be classed

+ d m c 11-31

2 D.B. 150 th.

B.H. 5/10/31 J.H.D.



© 2021

Lloyd's Register
Foundation

W252-0020