

Rpt. 8.

(Received at London Office)

No. 1073

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 3-6 1942. When handed in at Local Office 19... Port of Reykjavik

No. in Survey held at Reykjavik. Date, First Survey Last Survey 6-1942

Reg. Book. 60390 on the Wood, Iron or Steel s.s. "PERSIER". (No. of Visits)

TONNAGE: - Built at Newcastle. By whom Northumberland S.B.C. Ltd. When 1918-6

GROSS 5382 Owners Cie Maritime Belge (Lloyd Royal) Owners' Address

UNDER DK. 4792 Managers Agence Maritime Internationale Port belonging to Antwerp.

NET 3292

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell/Dor/DBa feet; uE & B feet; f feet

capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Report, No. 1000 Port Rjk

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any).

+ 100 FT 8.40.	+ LMC.
S.S. Ant. No. 3-30.	MS. 10.38.
S.S. Ant. No. 2-38.	BS. 9.40.
	T.S.C.L. 7.40. ✓

Age cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DESCRIPTION OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

GENERAL CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Fastenings	Cement or Asphalt	Oil Bunkers	Boats
Plating	Rudder	Scuppers	Masts, Yards, &c.
in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Frames	Windlass	Hatches	Equipment letter
inals	Have pumps been examined and found efficient?	Planking	Anchor, No. of
ses	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
ottom Plating	Have Watertight Doors been examined and found efficient?	Treenails	length mean diam. (on board.)
Tanks been examined internally?	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Tanks been tested?	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
		" " at other places	Standing and Running Rigging
		Stringers, Clamps & Shelves	Sails
		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee (per Section 29)	£	:	:	Fees applied for,
Damage or Repair Fee (if any)	£	:	:	19
Expenses (if chargeable)	£	:	:	Received by me,
Surveyor's Fee (if any)	£	:	:	19

Committee's Minute note of Deferred for repairs

Character Assigned



Is Certificate required? If so, to be sent to