

3.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to flow through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is 1st, 2nd, or 3rd bower.

Water tight doors and rudders examined under working conditions and found in order.

REPAIRS WEAR & TEAR.

TANKS: Tank under engine storeroom side 3 floors
Top part removed, and reinforced in energy

I.
Continuation of Report No. 6690 dated 7/7/24 on the

Forward Wills Bulwark part side, hatch way ways
at hold and bridge deck ward bulk head
The starboard side found plates and angles
etc. same bent damaged during bad weather
the last voyage and now repaired as follows:
at side bulwark plate main rail and bulwark

W25'8 - 0202 2/3