

Silverland

Nov. 97250.

It is submitted the Surveyors be requested to state the thickness of the boiler tubes, as this information has been omitted from the report.

The approval plan shows the  $1\frac{3}{4}$ " tubes to be .1645" and .1345" thick and the  $1\frac{1}{4}$ " tubes .1132".

Lr 14/3

L.L.  
13/3/39.

© 2019

Lloyd's Register  
Foundation

W261-0083