

of Ship Surveyor Nov 30th 14.

Received from Chief Ship Surveyor

NAME Steel S. S. "Stockwell" Rpt. Sld No. 26290

Requests of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

vey 1st Entry

It is submitted that before this case receives the consideration of the Committee, the Surveyor should be requested to state whether he is correct in reporting the spacing of the shell rivets through the frames as being $6\frac{1}{8}$ ".

The 'maship' section, the sketch of pillars & girders and the amended girder plan should be returned to the surveyor & he should be requested to indicate on the plans which arrangement has been adopted.

A.P.
30.11.14

The surveyor should also be requested to forward a letter from the owners agreeing to the omission of the intermediate bulkhead in No 2 hold.

A.P.
30.11.14

Lr. 1-12-14.



© 2019

Lloyd's Register
Foundation

W262-0009

BEAMS, Poop Deck, Angle, Bulb Angle, Plate,

Tee Bulb, or Channel

8 1/2 3.46 8 1/2 3.46

Bridge Deck Stringer Plate, br'dth & thickness