

F.E.

Received by Chief Ship Surveyor 5. 4. 04

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME See. S.S. "Björn" Report Cpu No. 1907

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>✓</i>	<i>✓</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>deep (channel) framing, increased</i> (viz., ordinary, deep, zed, channel or bulb-angle). <i>1/20" in thickness &amp; engorgement for</i> <i>deficiency in side stringers.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\nabla$  100 A 1 ("Steel") as recommended.

 $\nabla$  100 A 1 ("Steel")152 (Ste)  $\nabla$  deep framing.

M.B = Call DB a 40' a EYB 63' f94' 3496 FPT 306 APT 156

FK 48H Cam. Lloyd AYCP P 22' B 60' F 26'

© 2019 *5/4/04*Lloyd's Register  
Foundation

W263-0023