

Rpt. 8.

(Received at London Office)

L.A. No. 9336

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report 19... When handed in at Local Office 19... Port of Malta

No. in Survey held at... Date, First Survey... Last Survey... 19...  
Reg. Book. 33044 on the Wood, Iron or Steel S.S. "SELLINGE"TONNAGE :  
GROSS 2327  
UNDER DK 1789  
NET 1261Built at Sunderland By whom J. Priestman & Co. When 1916 7  
Owners Constants (South Wales) Ltd. Owners' Address  
Managers H. Constant Port belonging to London

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

LDBorDBa feet; uE & B feet; f feet  
Capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 2771 Port S.B.

Particulars of Classification (which must be inserted  
precisely as in Register Book & Supplements)

CHARACTER.	Machinery and Boiler
for Special Survey.	Surveys
Date of last Survey and of	(Including date of N.B., if any).
Periodical Surveys.	
+ 100 A1 2-43	+ LMC
SS 8th No 3-4-29	MS 3-38
SS 6th No 2-38	BS 2-43
Examined 6-42	TS CL 2-43

CARGO BATTENS NOT FITTED.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he  
offered his services for this purpose and to whom and why they were declinedSociety's Freeboard (if assigned) as  
painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

ARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

## GENERAL CONDITION OF THE

Bulkheads	Engine Room Skylights	Copper, or Y.M.
Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Rudder	Scuppers	Boats
Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Windlass	Hatches	Condition, how ascertained
Have pumps been examined and found effi-	Planking	(State if wedges removed.)
cient?	Caulking	Equipment letter
Have Sluice Valves been examined and found	Treenails	Anchors, No. of
efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Have Watertight Doors been examined and found	Transoms, Pointers & Crutches	" length mean diam.
efficient?	Timbers of Frame at openings	(on board.)
Have Ventilators and their Coamings been	" at other places	" Rule length size
examined and found efficient?	Stringers, Clamps & Shelves	Chain Locker
Air and Sounding Pipes	Salting	Hawsers & Warps
Doubling Plates under Sounding Pipes	(State if examined.)	Standing and Running Rigging
		Sails

## General Observations, Opinion as to Class, Recommendation, &amp;c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon  
this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of  
survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee (per Section 29)	£	:	:	Fees applied for,
Damage or Repair Fee (if any)	£	:	:	10.
Expenses (if chargeable)	£	:	:	Received by me,
Surveyor's Fee (if any)	£	:	:	10.

Committee's Minute

Fracter Assigned

FRI. 5 NOV 1916

Deferred to  
drydock? repairs & G/E

Surveyor to Lloyd's Register of Shipping.



© 2019

Lloyd's Register  
Foundation

Is Certificate required? If so, to be sent to

8110-6922