

(Received at London Office

24 DEC 1943

2650 on the Machinery of the Wood, Iron or Steel *S/S VIVA*

Gross 3798 Vessel built at Tredikstad By whom Tredikstad Mx. Bldg Co When 1938.5

Nominal	350	Bailers when made (Main)	1938	(Donkey)
---------	-----	--------------------------	------	----------

1st Report No. _____ Port _____

articulars of Examination and Repair's (1) any ~~from the Rep. History~~ p+100 H1 with HMC 538
radical Surgery when held must be reported in detail and seriatim in the terms of the Rules. State clearly the

damage cases where the Surveyor has not made a special damage report he is required to state whether he

as a damage report made by anyone else? If so, by whom? _____

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No 538 Walnut

" " Donkey "

his was not done, state for what reasons? *not prepared for survey*

1 what parts of the Boilers could not be thus thoroughly examined?.....

te latest date of internal examination of each boiler..... Present condition of funnel(s).....

1 the Surveyor examine the Safety Valves of the Main Boiler?..... To what pressure were they afterwards adjusted under steam?.....

1 the Surveyor examine the Safety Valves of Donkey Boiler?..... To what pressure were they afterwards adjusted under steam?.....

1 the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?.....✓....., and of the Donkey Boilers?.....✓.....

1 the Surveyor examine the drain plugs of the Main Boilers?....., and of the Donkey Boilers?.....

the Surveyor examine all the mountings of the Main Boilers?, and of the Donkey Boilers?

Is screw shaft now been drawn and examined? no Is it fitted with continuous liner? ✓ Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

shaft now been changed?..... If so, state reasons.....

Is the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted in the liner and on the shaft to permit of it being efficiently lubricated? } ✓
8"

Engine parts, when referred to by numbers, should be counted from forward

o. did the Surveyor examine the generators, motors, switchgear, cables and fuses?..... *Yes*

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.....

how done: Vessel placed on dry dock outside latrine on all hand in land order

Electric installation examined throughout and measured test.

General Observations, Opinion and Recommendation:— The machinery of this vessel

in good working condition and is eligible in my opinion to remain

vey Fee (per Section 29)..... ~~\$~~ 50.00 } Fees applied for

Committee's Minute _____ NEW YORK DEC 1 1943 _____ Lloyd's Reg

W267-0006

W267-0006

L.S. no 1 den 5.42

Ms. partly held 11.42 advanced

End 11.43

Noted

Thus

3.1.44



© 2019

Lloyd's Register
Foundation