

January. TAKORADI. No.1 Main bearing, wear down = .0015.

~~January~~ ACORA.

No.2 Main bearing, wear down = .003.

No.3 " " " "

WOKINGHAM COPY.

~~January~~

No.3 Crosshead pins and bearings metal of bottom halves.

No.3 Crankpin and bearing. Top half bearing cracked and loose - recommend it to be changed on arrival, same part.

~~February~~ ALABAMA.

No.6 Crosshead pins and bearings.

No.6 Crank pin

30th April, 1941.

Dear Sir,


With reference to Liverpool Report No.115893 on the Motorship "DUNKWA", I may say that it is considered a fee of £5. should be charged for the portion of the Continuous Survey of the oil engines now held.

I am, Dear Sir,
Yours faithfully,

Clerk to the
Classification Committee.

*Dunkwa 115893
Rebanded
for £5 fee to be charged
1/2/41*

The Secretary,
LIVERPOOL.



© 2021

Lloyd's Register
Foundation

W 27-0049

W 27-0050