

COPY.

# Lloyd's Register of Shipping.



Port Willemstad, Curacao. N.W.I.

Port Willemstad, Curacao. N.W.I.

4th September, 1944.

This is to Certify that I have

Surveyed the T.S.M.V. "AMPETOO" 8718 Gross Tons of Antwerp,  
afloat in Curacao. N.W.I. on 23rd August 1944 and subsequently  
for repairs to cargo lines in Pumproom and cargo tanks,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be retained as now

classified without fresh record of survey subject as at present to permanent repairs to buckled forecastle side plating (p.s) indented plating and structure in way of Nos. 4 & 5 summer tanks and fractured plate in G strake (p.s) in way of midship pumproom first convenient opportunity. Indented plate G.4 (s.s). Bent lower rudder to be dealt with at Owners convenience.  
being fit to carry petroleum in bulk.

*P.A. Vesting*  
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

B.) 10M-10-42  
PRINTED IN U.S.A.

W270-0121

Damage or Repair Fee (if any) £ 75.00 4.9.1944

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MEMORANDUM

26  
Register  
Vo  
Classi  
in Re  
ER  
Survey  
ey and  
rveys.  
3.4  
d  
11  
3-  
P.t.  
W  
E.34  
annel  
sted un  
sted un  
Boilers  
Boilers  
Boilers  
fitted  
bing  
the a  
ciently  
ter bea  
r power  
Near  
spr  
re  
d  
ti  
IS  
m  
l  
m  
Register  
Foundation