

COPY.

18th March, 1942.

Dear Sirs,

With reference to the case of the motorship "ABEEKERK", I beg to acquaint you the Committee have now had before them a report received from the Society's Surveyor at Port Natal, from which it appears the vessel has been examined afloat and on account of leakage, temporary repairs have been effected to shell plate No.1 in 5th strake below sheer, port side aft. It is recommended permanent repairs be carried out at the first opportunity.

The following note is being added to the memorandum in this office regarding the case:-

"Permanent repairs require to be effected at the first opportunity to shell plate No.1 in 5th strake below sheer, port side aft."

I am, Dear Sirs,
Yours faithfully,

Clerk to the
Classification Committee.

The Netherland Shipping & Trading Committee Ltd.,
Technical Dept.,
5/6, Crosby Square,
Bishopsgate,
LONDON, E.C.3.

Lloyd's Register
Foundation

W274-0002