

Chief Surveyors

Received from Chief Surveyors

SHIP NAME *Steel S.S. "VICTORITE"*Report *NK*No. *20539***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report 24/5/92.)

Survey

When due

✱ 100-A-1. (Steel) Shelter Deck with freeboards

*'Carrying petroleum in bulk'*

2 Dks (Steel) &amp; Shelter Dk (Steel) &amp; Web frames, longitudinal framing

Cell IB &amp; FB 68' 199t, ITf 54' 646t, FPT 258t, APT 142t

FK, 19BH (A to Shelter Dk, 11 to Upper Dk, A to 2<sup>nd</sup> Dk) . pt app pt Lem,

Ar CP, Mchly Aff

*See link  
27.10.21**NK  
20.9.21*

It is Concluded the Signs of Nos 8, 10, 12 & 13 Shell Longitudinals are as approved and not as Stated; the upper tween deck transverse, Spacing of Shell and tank top Longitudinals, Side Girders, Spacing of transverse at ends and bulk bars to bottom Longitudinals forward are as approved.

*S.O. 12/10/21*

© 2019

Lloyd's Register  
Foundation

W28-0010

W28-0011

... in more under framing, etc., on the first page.