

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to be repaired, if any, and, in detail, the nature and extent of the damage (the cause of which must be stated) detailed in the body of the report, should be stated. Also the dates and initials of any letters sent to the vessel.)

Subject is indented No 5 shell plate
sheer (P.S.) etc being dealt with
dry docking.

Report by Chief Ship Surveyor

SEL'S NAME

MARIE JOSE

Report by

Rou.

Society's Freeboard (if assigned) as verified

No. 2095
No 2109

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

ure of Survey

Damage through

collisions and striking a submerged object

now repaired as follows:-

	Shell Plates	Main Frames	R Frames	Floors & Bracket Floors	Inner Bottom Plates	Deck Plates	Beams
Renewed	14	3				1	
Removed and faired or repaired.....	10						
Faired or repaired in place.....	5	9					

Other items:-

Vessel placed in dry dock

Bottom Coated

Stem repaired.

The No 5 shell plate in 4th Strake below sheer (P.S.) etc as above have now been dealt with.

It is submitted the vessel is worthy to remain as classed with

record of Survey 1.40 without special condition

100 A1

with Freeboard

1.40 Rou

without etc



© 2020

Lloyd's Register
Foundation

W283 - 0016

15.2.40

Surveyor to Lloyd's Register