

COPY.

12th March 1920.

Messrs R. Williamson & Son,  
WORKINGTON.

Dear Sirs,

Referring to your S.S. "DYNAMO" No. 230 and to the discovery when being launched of a hole through the starboard shell plating which had not been drilled through the double bottom margin plate fore and aft angle, I beg to state that I have to recommend that the vessel be placed in dry dock to enable this matter to be put right, before I can report favourably on her to the Committee with a view to obtaining the Society's classification, and I shall be glad if you will kindly inform me as to your intentions.

Yours faithfully,

Sgd. Thomas S. Shute.



© 2019

Lloyd's Register  
Foundation

W29-0037