

2m. 12.42.

2761 XNNE

ent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "EMPIRE IMPALA" REPORT N.Yk. No. 43426

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey Damage When the

Subject to permanent repairs to indented shell plate No.2 in 3rd strake below Upper deck sheer (p.s.f.) and longitudinal frame in way at the Owners' convenience, to 15 fathoms of chain cable being repaired at the first opportunity and to (45 fathoms of chain cable being supplied).



© 2019

Lloyd's Register
Foundation

W29-0120