

REPORT OF THE
Date of writing Report 24. 11 1938 When handed in at Local Office 24. 11 1938 Port of Grimsby
Date First Survey + Last Survey 18. 11 1938

1838 on the Wood, Iron & Steel SC "Northern Ble" YEAR. MONTH.
A. G. Seebach When 1936 . 12

CROSS
OWNERS *H. Markham & Co*
UNDER DE. *531*
209
MANAGERS *H. Markham Cook*
Port belonging to *London*

$VB = CellDBorDBa$ feet; $uE\&B$ feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.
 should be underlined.

precisely as in Registered Book & Supplements

CHARACTER.
 * for Special Survey.
 Date of last Survey and of

Years assumed now expired.

Machinery and Boiler Surveys
 (including date of N.B. in an

Cast Report, No. 2075 1972

Stm Trawler 4.38

See

on damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Now done! - Vessel placed on slipway, bottom & rudder cleaned & re-coated.

SUMMARY OF DAMAGE REPAIRS:—		Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed	...								
Removed and Paired or Repaired	...								
Faired or Repaired in place	...								

PRESENT CONDITION OF THE		State if Tanks have been examined inside		Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	good	State if Tanks now tested	✓	Dblg. Plates under Sounding Pipes	(State if on Felt.)
Caulking of Decks	"	Bulkheads	✓	Engine Room Skylights	When put on, Month
Coamings	"	Ceiling	✓	Coal Bunkers, Open'gs, Lids, &c.	Year
Beams & Fastenings	✓	Cement or Asphalt	✓	Oil Bunkers	Boat
Outside Plating	good	(State which.)	✓	Scuppers	Masts, Yards, &c.
" " in way of sidelights	✓	Rudder	good	Cargo Hatchways	Condition, how ascertained
Breasthooks	✓	Steering gear and its connections	"	Hatches	(state if wedges removed)
Transoms	✓	Windlass	"	Planking	Sails
Frames	✓	Have pumps now been examined and found efficient?	✓	of Wood Vessels	Equipment letter
Reverse Frames	✓	Have Sluice Valves now been examined and found efficient?	✓	Caulking	Anchors, No. of
Longitudinals	✓	Have Watertight Doors now been examined and found efficient?	✓	Treenails	Chain Locker
Transverses	✓	Have Ventilators and their Coamings been examined and found efficient?	✓	Breasthooks & Stemson	Cables (State if now ranged)
Floors	✓			Transoms Pointers, & Crutches	" length mean diam.
Keelsons	✓			Timbers of Frame at openings	(on board)
Stringers	✓			Ditto Ditto at other places	" Rule length size
Inner Bottom Plating	✓			Stringers, Clamps & Shells	Hawser & Warps
				Salting	Standing and Running Rigging
				(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24.

This vessel is eligible, in my opinion, to remain a classed & to have record of Survey 11.38

Survey Fee (per Section 20)	£	:	:	Fees applied for,
				19
Special Damage or Repair Fee (if any).....	£	:	:	Received by me,
(per Sec. 20)				19
Travelling Expenses (if chargeable)	£	:	:	
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute

Character Assigned

Fees applied for,

Received by me,

Surveyor to Lloyd's Register of Shipping

Clare Bell

© 2019

Lloyd's Register
99-0004
Foundation