

V.

18.9 JUL 1945

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME "CORONDA" REPORT Grk. No. 23067

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey Further Modified Gen. Exam. When due 3.45

"EXAMINED (Mod.) 6.45" 12 MOS.
to (redress) bridge deck plating

Subject to permanent repairs to coal bunkers, to


(holed) F'cle side plate No.2 in 1st strake above sheerstrake (s.s.)

Bridge side plating etc. (p.s.) and Poop sheerstrake plate (port quarter) at the first opportunity, and to (60 fathoms of chain cable being supplied)."

"Examined (Mod.) 6.45"

SR

12.7.45



© 2020

Lloyd's Register
Foundation

W300-0126

oil fuel Depot Plup.