

Chief Ship Surveyor 29.3.15

Received from Chief Ship Surveyor

NAME Sheess Bronze Wings Rpt. Ave No. 67318 }
67319 }

Marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

Transverse No. 77.78

Depth "d" 22.7

Planing: Table No. 3 page 16.

Description Bull angle as approved

Longitudinal No. 29167

Proportions Length = 10.95
Depth =

Sheerstrake: as per Rule.

This vessel is reported to have encountered heavy weather when leaving the tyne and to have slipped 2 anchors & 150 faths of chain cable.

The Anchors & 150 faths of chain have been replaced but in the case of the 2nd bow anchor it appears that the drop test on the cast steel anchor head was carried out by a Surveyor to the British Corporation. It is however, submitted this anchor might be accepted.


This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100A-1 (Steel) Shell Deck with freeboard," as recommended. The Summer freeboard of 2' 10 1/2" from centre of disc to top of statutory deck line at upper deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, shown on the accompanying verification form to be inserted in the certificate of classification.

∇ 100A-1 (Steel) Shell Deck with freeboard

1 Deck (Steel) & Shell Deck (Steel)

WB = class B a 125' a 240' 42" f 163' 1182E, APT 143E

FK. 6BH. Cen. Lloyd's Reg.



© 2019

Lloyd's Register Foundation

616