

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 22/3/1938. When handed in at Local Office 22/3/1938. Port of PIRAEUS.
 No. in Survey held at Piraens Date, First Survey 11th March Last Survey 12th March 1938
 Reg. Book. (No. of Visits, 2)

3149 on the ~~Wooden~~ Iron or Steel TWIN SC SCHOONER YACHT "KAREN"
 TONNAGE:- Built at GOSPORT By whom Camper Nicholson & Co. When 1923 7
 GROSS 200.89 Owners Karfik 62. La Owners' Address 91 Bishopsgate, London E.C.2
 THAMES MEASUREMENT 225 (if not already recorded in Appendix of Register Book).
 NET 101.49 Managers Port belonging to London.

Surveyed ~~At sea~~ in Dry Dock? Dry Dock Name of Dock No 2 Dry Dock Destined Voyage

WB = Cold B or DBa feet; uE & B feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Years Allowed now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A.1. S.36.		LMC 3.35.
SS Gos No 3 - S.36		+ LMC (M) 1.38
AS		S 5.35 C.L.
Oil engines		Oil Eng
AS 5.37		

N.B. - All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4594 Port Pir

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined Copy of

damage report herewith.

Was a damage report made by anyone else? If so, by whom? No.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Damage & Docking.

On account of damage, stated caused by vessel grounding at the entrance to Turcolimani Harbour, near Piraens, on 2nd October 1934: see Piraens Report No 4538:

NOW DONE. Vessel placed in dry dock, bottom & under keels cleaned & examined, & found no damage had been sustained. Vessels afterwards recoated.

NOW DONE FOR CONDITION. Vessel placed in dry dock, bottom & under keels cleaned, examined & recoated. The deck, masts, duck erections, machinery space, P.T.O

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed ...								
Removed and Fair'd or Repaired ...	✓	✓	✓	✓	✓	✓	✓	✓
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	Good	State if Tanks have been examined inside	✓	Dblg. Plates under Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels	✓
Caulking of Decks	"	State if Tanks now tested	✓	Engine Room Skylights	Good	(State if on felt.)	✓
Coamings	"	Bulkheads	Per Report Good	Coal Bunkers, Open'gs, Lids, &c.	Good	When put on, Month	Good
Beams & Fastenings	Good	Ceiling	✓	Scuppers	Good	Boats	Good
Outside Plating	✓	Cement or Asphalt (State which.)	Good	Cargo Hatchways	✓	Masts, Yards, &c.	Good
Breasthooks	✓	Rudder	"	Hatches	✓	Condition, how ascertained	From deck
Transoms	Per report Good	Steering gear and its connections	"	Planking of Wood Vessels	✓	(State if wedges removed)	✓
Frames	✓	Windlass	"	Caulking	ditto	Sails	✓
Reverse Frames	✓	Have Pumps now been examined and found efficient?	✓	Treenails	ditto	Equipment letter	✓
Longitudinals	✓	Have Sluice Valves now been examined and found efficient?	✓	Breasthooks & Stemson	ditto	Anchors, No. of	2315
Transverses	Per report Good	Have Watertight Doors now been examined and found efficient?	✓	Transoms, Pointers, & Crutches ditto	✓	Cables (State if now ranged)	Yes
Floors	"	Have Ventilators and their Coamings been examined and found efficient?	✓	Timbers of Frame at openings ditto	✓	length 14 fms size 3/4"	✓
Keelsons	"			Ditto ditto at other places ditto	✓	Rule length 135 fms size 1/2"	✓
Stringers	"			Stringers, Clamps & Shells ditto	✓	Hawser & Warps	Sufficient
Inner Bottom Plating	✓			Salting ditto	✓	Standing & Running Rigging	Good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND15, &c."

This vessel so far as now seen, is eligible in my opinion to remain as classed, & to have fresh record of survey 3.38.

Survey Fee (per Section 20)	£	3	0	0	Fees applied for, 22/3/1938
Special Damage Repair Fee (if any) (per Sec. 20)	£	0	3	0	Received by me, 19
Travelling Expenses (if chargeable)	£				
Second Surveyor's Fee (if any)	£				

Committee's Minute

FRL 8 APR 1938


Character Assigned

100 A1 (Yacht) subjed

Note AS 3.38

AS 3.38

P. F. Balfour.
 Surveyor to Lloyd's Register of Shipping.



Lloyd's Register
 Foundation

for issue if in order

B4.3

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]