

Reversed Frame, Angles..... 3 01 7-9' 3 01 7-9'

Rider Plate.....

on, 1, 12.

to Chief Surveyors.....

Received from Chief Surveyors.....

SHIP'S NAME STEEL S.S. "WEST QUECHEE" Report Pld. No. 563

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey.....

When due.....

The committee have agreed to accept anchors tested at San Francisco, subject to the machine used being examined & reported upon.

The Downston Pump has been dispensed with for the present.

100 A.1. (steel)

2 Dks. (steel).

Cell DB 355' 1130t. MT 29' 745t. FPT 132t. APT 143t.

FK. 7 BH. pt.com. A. & C.P. P 44', B 115', F 47'.

© 2019

Lloyd's Register
Foundation

2.7.19

Remainder in Holds.....

Upper Deck, Side Hatchways, Bulkheads, etc.

Angles on ditto, No.....

Tie Plates, outside Hatchways.....