

Subject to set up keel plate N° 2 from forward being repaired at the first convenient opportunity.

30 OCT 1940  
7

Inspected by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME ARINIA Rpt. Cff No. 53650

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32).

Year of Survey DAMAGE AND PART 1<sup>st</sup> S.S. No. 1 due 7.40

Damage through Grounding, & whilst pumping up N° 3 port wing tank.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- minor repairs effected.  
Temporary repairs effected to slightly indented bottom plating & internal structure in way of & buckled bottom & side transverses & side longitudinal girders in N° 3 port cargo tank. The Surveyor recommends permanent repairs be effected at the Owner's convenience.

N° 2 keel plate, as above, has not been dealt with, efficient meantime.

Vessel placed in dry dock, bottom cleaned & coated.

The 1<sup>st</sup> S.S. No. 1 due 7.40 has also been partly held and the following repairs done due to wear and tear:-

minor repairs effected.

It is proposed to complete the survey before the expiration of the year of grace


~~It is submitted this proposal might be approved, and the vessel be allowed to remain as classed record of Survey, notation of S.S. No. being deferred until completion of same.~~

Action be deferred.

ASB  
30.10.40

The following remains to be done to complete the 1<sup>st</sup> S.S. No. 1

viz:- Forward deep tank to examine internally.



© 2020

Lloyd's Register Foundation

W335-0039