

"EMPIRE WARRIOR"

(2)

be received, the vessel will be eligible to be classed 100 A- (See endorsements dated 5.12.39 and 12.12.39)

The Leith Surveyors now report the vessel examined afloat and in dry dock, bottom cleaned and coated and the requirements of a Second Special Survey No 3 carried out.

The thicknesses of the shell plating ascertained by drilling as shown above appear to be satisfactory.

On account of wear and tear repairs to shell plating, framing, floors, bulkheads, tunnel, bunker trunks, deck plating, hatchways, ventilators, air pipes, steering connections and minor repairs effected.

Additional pillars have been fitted in the combined poop and bridge 'tween deck above the existing widely spaced hold pillars and in the forecastle to provide effective support.

Alterations to a number of small hatchways, superstructure bulkheads etc. carried out.

Cargo battens have not been fitted.

The equipment is not equivalent to the requirements of this Society and no particulars of its origin and testing have been furnished.

It is submitted the vessel appears worthy to be classed 100 A- with record of survey 2.40 and notation of S.S. 2nd No 3-2,40

100 A-

1 Dk.

Cell DB 199' 35lt, FPT, 38t, APT 55t.

FK, 4 BH, Cem.

P&B 190' F 33'

O.L. 255.5'

2,40 Lth.

S.S. Lth. 2nd No.3-2,40

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



© 2020

Lloyd's Register
Foundation

6.3.40

W34-0006(212)